

Technical *Info*

Change of idler pulley CT 975 K1 to CT 975 K3 - Opel 1.6 / 1.8 16 V

Fig. 1
Pulley to be replaced



Problem:

The idler pulley included in the kit for the type delivered is different to the one installed in the vehicle.

Cause:

According to the manufacturer, the new pulley with plastic barrel jacket (55373) must be installed when the belt is changed instead of the previous metal version (55333).

Fig. 2
New idler roller



Solution:

The new pulley is now equipped with a pre-mounted bolt and can be used directly.