



febi 22410

to fit:
Renault Scenic 1 and Megane 1



Ref. no. 77 00 430 766 S1



Smart Repair Solutions for Professionals!

febi is your partner for efficient repairs!

The ball joint can be replaced without removing the complete control arm! However, the vehicle manufacturers only sell it with the complete control arm, even though the ball joint is screwed on in production and can therefore be replaced separately.

febi offers the right solution!

The repair kit 22410 contains the ball joint and all bolts and nuts; all of the required quality - it is not necessary to replace the complete control arm. This also saves your customer money.



Ball joint repair kit febi 22410



Control arm febi 19647



Control arm febi 19646

Attention! Danger of Confusion!

The control arms 77 00 430 766 S1 (febi no. 22410) and 77 01 468 883 (febi no. 10640) seem identical on first glance. However, the diameters of the fixing holes are different! The bore holes of control arm 77 00 430 766 S1 (febi no. 22410) have a diameter of 12mm, the bore holes of control arm 77 01 468 883 (febi no. 10640) have a diameter of 10mm. Some parts identification media falsely allocate control arms with 10mm bore holes to these vehicles.

A mix-up presents a severe safety risk!

Of course, febi's range also includes the complete control arms febi 19646 and 19647.

For more technical information please visit: partsfinder.bilsteingroup.com