

NEW PRODUCT HIGHLIGHT | JUL2019

SWAG[®]

SWAG 10 10 5765

to fit:
Mercedes Benz C class C203 model 2000 >



Steering Column Switch assembly

Function

Multifunction column switch, to control the directional indicator, lights and windscreen wipers.

Cause of failure

The multifunction switch loses functionality; the cause of this issue, is that the wiring which goes into the stalk/lever breaks due to continuous movement and use, causing an open circuit.

For more technical information please visit: partsfinder.bilsteingroup.com