



Service Info



Repair set 533 0116 10

for the Mercedes-Benz and Volkswagen assembly drive

Manufacturers: Mercedes-Benz, Volkswagen

Models:

Mercedes-Benz: C-Class (W202/S202/W203/
S203/C203),
CLK (C208/A208),
E-Class (W124/S124/C124/A124/
W210/S210),
SLK (R170),
M-Class (W163),
V-Class/Vito (638/638/2),
Sprinter (901/902/903/904)

Volkswagen: LT 28-35 II, LT 28-46 II

Engine code:

Mercedes-Benz: M111

Volkswagen: AGL

Part no.: 533 0116 10 (SET)

Contents of repair set 533 0116 10:

- 1 tensioning unit 533 0084 30
- 1 damper 533 0055 20
- 1 rolling element Ø 110x29mm 531 0551 20
- 1 nut M10*
- 1 cover Ø 50x11mm*
- 2 screws M8x74mm*
- 1 screw M8x25mm*
- 1 screw M8x20mm*
- 1 screw M8x35mm*
- 1 spring washer Ø 8,2x16mm*

*not available individually



Image 1: 533 0116 10 – INA repair set for the assembly drive including fixing screws

All components of this assembly drive (image 1) are designed to achieve the same service life and are subject to the same amount of wear.

For this reason, Schaeffler Automotive Aftermarket is the first manufacturer in the spare parts market to offer a full repair set (image 1) for the assembly drive of the vehicles listed above.

The repair kit replaced the tensioner arm 531 0563 30 and includes the pulley, the damper, the tensioning unit and all mounting parts.

Schaeffler Automotive Aftermarket recommends that all belt drive components are replaced when working on the assembly drive.

Note the specifications of the vehicle manufacturer!

Spare parts and technical information can be found under www.schaeffler-aftermarket.com or www.RepXpert.com.

Phone: +44 (0) 14 32 264 264*
Fax: +44 (0) 14 32 375 760
info@luk-as.co.uk
www.schaeffler-aftermarket.com

* Calls from within the UK 08457 001100

SCHAEFFLER
AUTOMOTIVE AFTERMARKET

