



INA Service Info



Overrunning alternator pulley 535 0071 30

Visual differences

Manufacturer: Cadillac, Opel, Saab, Vauxhall

Models:

Cadillac: BLS
 Opel: Signum, Vectra C, Zafira B
 Saab: 9-3
 Vauxhall: Signum, Vectra MkII, Zafira Mk II

Engines: 1.8, 2.0, 2.2 petrol engines

Part no.: 535 0071 30

For current listing refer to catalogue media



Fig. 2: 535 0071 30 – new design with protective cap

As part of the on-going development of our products, the over-running alternator pulley 535 0071 30 has been modified.

The previous design without protective cap (Fig. 1) is being replaced by a new design with a protective cap (Fig. 2). During the transition phase, stocks may become mixed.

Both design configurations meet the technical specifications and can be used without restriction.



Fig. 1: 535 0071 30 – old design without protective cap

Please observe the vehicle manufacturer specifications!

You want more? We can help!

Phone: +44 (0) 1432 264 264
 Fax: +44 (0) 1432 375 760
 aftermarket.uk@schaeffler.com
 www.repxpert.co.uk

SCHAEFFLER
REP>XPERT