

# SKF Technical Bulletin

## VKBA 3511 – Mandatory replacement of the locking washer



OPEL/VAUXHALL Astra G, Astra MK IV



**Mandatory replacement of the locking washer during the wheel bearing fitting**



OE Nb: 16 03 209, 9117620

To ensure a complete and professional repair, SKF has added a locking washer in the wheel bearing kit from batch code 240 R. It is mandatory to replace the old locking washer as it can be damaged during the bearing removal or when fitting the new one.

### VKBA 3511



*Locking washer included in the wheel bearing kit*

**YouTube** [Click here to watch SKF technical videos on Youtube!](#)

© SKF Group 2019

The contents of this publication are the copyright of the publisher and may not be reproduced (even extracts) unless written permission is granted. Every care has been taken to ensure the accuracy of the information contained in this publication but no liability can be accepted for any loss or damage whether direct, indirect or consequential arising out of the use

