

# Claw 100

## Ampere Pliers

Especially suited to precise measurements in the lower current area. This allows closed current measurements to be conducted without having to separate the circuit.

- automatic selection of measurement range
- automatic switch-off after 15 minutes idle
- values saved (data hold)
- delivery includes measuring cable and bag

**Gauge:** with LCD display  
**Registration Type:** CE approved  
 GS checked  
**Required appliance battery:** AAA (Micro)  
 Nickel Metal Hydrid Battery (NiMH)

**WxHxD:** 71 x 226 x 38 mm  
**Weight:** 75 g  
 200 g  
**Info:** with diode test function  
 with continuity test function

Measurement range (AC) V	Measurement range (DC) V	Measurement range (AC) A	Measurement range (DC) A	Measurement range $\Omega$	DU	Article no.
4 40 400 600	0,4 4 40 400 600	40 100	40 100	400 Ohm to 40 MOhm	1	95980776

